




CHECK MASTER



horizontal orientation



vertical orientation



6882-600A

- To check the accuracy of table movement of machine tools, to calibrate height gages and CMMs
- Ceramic gage blocks
- Can be used in either vertical and horizontal orientation
- Supplied with manufacturer inspection certificate

(mm)

Code	Range	Step	Accuracy	Parallelism of blocks	L	L1	H	W
6882-300A	300mm	10mm	±2.5µm	1.2µm	350	310	49	45
6882-450A	450mm	10mm	±3.5µm	1.5µm	510	470	54	50
6882-600A	600mm	10mm	±3.5µm	1.5µm	650	610	54	50